



Erosion created by Tropical Storm Irene



Three stone stairs built at the entrance to the reroute on the Old Bridle Path.





Approximately 30 feet of "turnpiking" on the Old Bridle Path reroute.



Stones used to stabilize a bank affected by an uprooted tree.





More reinforced banking.



A segment of new treadway along the reroute.



This bridge abutment also needed reconstruction after Tropical Storm Irene.